

| 注意事項 (此是大方向，並非一定就是此零件故障 以服務人員實際更換零件為主) |  |  |
|--|--|--|
| 故障碼                                    | Explanation  | 中文說明   |
| E 100                                  | Laser power has weakened   | ROS雷射單元相關零件故障                                  |
| E 300                                  | Warm-up has not completed within the specified time.   | 加熱/電源板單元相關零件故障                                 |
| E 500                                  | Abnormal rotation signal of Main/Sub/Deve Motor (DRIVE ASSY MAIN) or the PH Motor (DRIVE ASSY PH) is detected. | 相關主輔驅動馬達問題                                     |
| E 550                                  | Abnormal rotation signal of the FAN MAIN/FAN DUP is detected.  | 相關風扇零件故障                                       |
| E 600                                  | Output of the ADC Sensor inside the TRANSFER UNIT is decreased   | 轉印單元相關異常                                       |
| E 610                                  | High temperature, low temperature, or high humidity that goes out of range.                                    | 溫濕度相關值測故障                                      |
| E 900                                  | NV-RAM in the PWBA MCU error   | 引擎相關參數錯誤                                       |
| E 901                                  | Firmware error   | 引擎韌體錯誤   |
| E 988                                  | Engine communication error   | 引擎板通訊錯誤  |
| C 0017                                 | CPU error (Interrupt exception)  | 主機板CPU 運算問題                                    |
| C 0088                                 | CPU error (System call exception)  | 主機板CPU 運算問題                                    |
| C 0089                                 | CPU error (Break point exception)  | 主機板CPU 運算問題                                    |
| C 0091                                 | CPU error (Disabled floating-point exception)  | 主機板CPU 運算問題                                    |
| C 0300                                 | CPU error (Reserved (undefined) exception)   | 主機板CPU 運算問題                                    |
| C 0301                                 | CPU error (Machine check exception)  | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0302                                 | CPU error (Data access exception)  | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0303                                 | CPU error (Instruction access exception)   | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0304                                 | CPU error (Alignment exception)  | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0305                                 | CPU error (Program exception)  | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0306                                 | CPU error (Trace exception)  | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0307                                 | CPU error (Performance monitor exception)  | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0308                                 | CPU error (System administration interrupt exception)  | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0309                                 | CPU error (Temperature management interrupt exception)   | 主機板CPU 運算問題 (更新主機板Firmware至最新版 )               |
| C 0800                                 | IPL error (Controller defective)   | P-ROM 沒裝或故障                                    |
| C 0998                                 | Engine communication error (Only when powering on)   | MCU板 或 主機板 通訊                                  |
| C 0999                                 | No Engine Flash ROM program data   | MCU板 或 主機板                                     |
| C 1002                                 | Standard RAM error (When the standard size is not determined, etc.)  | 主機板問題  |
| C 1010                                 | Verify error   | 主機板問題  |
| C 1020                                 | RAM error (Slot 0)   | 記憶體沒裝或記憶體壞或不相容 規格200Pin DDR RAM CL(核心電壓) =2.5V |
| C 1021                                 | RAM error (Slot 1)   | 記憶體沒裝或記憶體壞或不相容 規格200Pin DDR RAM CL(核心電壓) =2.5V |
| C 1100                                 | ROM checksum error (bit 0 ~ 15)  | 主機板ROM問題                                       |
| C 1101                                 | ROM checksum error (bit 16 ~ 31) (Font)  | 主機板ROM問題                                       |
| C 1120                                 | ROM checksum error (bit 0 ~ 7) (Program)   | 主機板ROM問題                                       |
| C 1121                                 | ROM checksum error (bit 8 ~ 15)  | 主機板ROM問題                                       |
| C 1122                                 | ROM checksum error (bit 16 ~ 23) (Program)   | 主機板ROM問題                                       |
| C 1123                                 | ROM checksum error (bit 24 ~ 31) (Program)   | 主機板ROM問題                                       |
| C 1170                                 | Optional Font ROM module checksum error  | 主機板ROM問題                                       |
| C 1180                                 | Optional ROM module A checksum error   | 主機板ROM問題                                       |
| C 1181                                 | Optional ROM module B checksum error   | 主機板ROM問題                                       |
| C 1185                                 | Unsupported ROM module   | 主機板ROM問題                                       |
| C 1200                                 | EEPROM write error   | 主機板問題  |
| C 1210                                 | EEPROM write count limit   | 主機板問題  |
| C 1400                                 | Engine initialization malfunction  | 主機板問題  |
| C 1500                                 | CCNV hardware error  | 主機板問題  |
| C 1550                                 | Compression SRAM initialization hardware error   | 主機板問題  |
| C 1600                                 | Video related hardware error (including PWM IC calibration error)  | 主機板問題  |
| C 1700                                 | Built-in network hardware error  | 內建網路卡問題  |
| C 1702                                 | Network board uninstalled  | 網卡未安裝  |
| C 1710                                 | Token Ring hardware error  | 內建網路卡問題  |
| C 1800                                 | SPD error of ROM module  | 主機板問題  |
| C 1999                                 | Other hardware error   | 主機板問題  |
| C 2000                                 | Software error   | 主機板問題  |