

注意事項 (此是大方向,並非一定就是此零件故障 以服務人員實際更換零件為主)			
故障碼	說明	說明	說明
E 100	SOS signal cannot be detected.	雷射光單元及其相關零件故障	
E 101	Abnormal high temperature was detected (at	加熱及其相關零件	
E 102	NV-RAM error	MCU BOARD EEPROM 錯誤	
E 103	The HOLDER ASSY CTD power has weak	碳粉濃度偵測相關零件異常	
E 104	Fan Motor failure.	風扇馬達相關零件異常	
E 105	Motor failure (Main Drive Motor/Deve Mot	主馬達/顯像單元驅動馬達/加入器驅動馬達帶動異常	
E 106	Firmware error	韌體故障	
E 107	Humidity of 100 % or more was detected.	濕溼度相關零件異常	
E 201	DEVE ASSY (Y) reached its end of life.	顯像單元-Y壽命到期	
E 202	DEVE ASSY (M)reached its end of life.	顯像單元-M壽命到期	
E 203	DEVE ASSY (M) and (Y) reached its end of	顯像單元-M-Y壽命到期	
E 204	DEVE ASSY (C) reached its end of life.	顯像單元-C壽命到期	
E 205	DEVE ASSY (C) and (Y) reached its end of	顯像單元-C-Y壽命到期	
E 206	DEVE ASSY (C) and (M) reached its end of	顯像單元-C-M壽命到期	
E 207	DEVE ASSY (C), (M) and (Y) reached its e	顯像單元-C-Y壽命到期	
E 208	DEVE ASSY (K) reached its end of life.	顯像單元-K壽命到期	
E 209	DEVE ASSY (K) reached its end of life.	顯像單元-K壽命到期	
E 210	DEVE ASSY (K) and(Y) reached its end of	顯像單元-K-Y壽命到期	
E 211	DEVE ASSY (K), (M) and (Y) reached its e	顯像單元-K-Y壽命到期	
E 212	DEVE ASSY (K) and(C) reached its end of	顯像單元-K-C壽命到期	
E 213	DEVE ASSY (K), (C) and (Y) reached its e	顯像單元-K-C-Y壽命到期	
E 214	DEVE ASSY (K), (C) and (M) reached its e	顯像單元-K-C-M壽命到期	
E 215	DEVE ASSY (K), (C), (M) and (Y) reached	顯像單元-C-M-Y-K壽命到期	
C 0017	CPU error (Interrupt exception)	主機板CPU 運算問題	
C 0088	CPU error (System call exception)	主機板CPU 運算問題	
C 0089	CPU error (Break point exception)	主機板CPU 運算問題	
C 0091	CPU error (Disabled floating-point excepti	主機板CPU 運算問題	
C 0300	CPU error (Reserved (undefined) exception	主機板CPU 運算問題	
C 0301	CPU error (Machine check exception)	主機板CPU 運算問題	
C 0302	CPU error (Data access exception)	主機板CPU 運算問題	
C 0303	CPU error (Instruction access exception)	主機板CPU 運算問題	
C 0304	CPU error (Alignment exception)	主機板CPU 運算問題	
C 0305	CPU error (Program exception)	主機板CPU 運算問題	
C 0306	CPU error (Trace exception)	主機板CPU 運算問題	
C 0307	CPU error (Performance monitor exception)	主機板CPU 運算問題	
C 0308	CPU error (System administration interrupt	主機板CPU 運算問題	
C 0309	CPU error (Temperature management inter	主機板CPU 運算問題	
C 0800	IPL error (Controller defective)	P-ROM 沒裝或故障	
C 0998	Engine communication error (Only when p	MCU板 或主機板	
C 0999	No Engine Flash ROM program data	MCU板 或主機板	
C 1002	Standard RAM error (When the standard s	主機板問題	
C 1010	Verify error	主機板問題	
C 1020	RAM error (Slot 0)	記憶體沒裝或記憶體壞或不相容	
C 1021	RAM error (Slot 1)	記憶體沒裝或記憶體壞或不相容	
C 1100	ROM checksum error (bit 0 ~ 15)	主機板ROM問題	
C 1101	ROM checksum error (bit 16 ~ 31) (Font)	主機板ROM問題	
C 1120	ROM checksum error (bit 0 ~ 7) (Program)	主機板ROM問題	
C 1121	ROM checksum error (bit 8 ~ 15)	主機板ROM問題	
C 1122	ROM checksum error (bit 16 ~ 23) (Progra	主機板ROM問題	
C 1123	ROM checksum error (bit 24 ~ 31) (Progra	主機板ROM問題	
C 1170	Optional Font ROM module checksum erro	主機板ROM問題	
C 1180	Optional ROM module A checksum error	主機板ROM問題	
C 1181	Optional ROM module B checksum error	主機板ROM問題	
C 1185	Unsupported ROM module	主機板ROM問題	
C 1200	EEPROM write error	主機板問題	
C 1210	EEPROM write count limit	主機板問題	
C 1400	Engine initialization malfunction	主機板問題	
C 1500	CCNV hardware error	主機板問題	
C 1550	Compression SRAM initialization hardware	主機板問題	
C 1600	Video related hardware error (including PW	主機板問題	
C 1700	Built-in network hardware error	內建網路卡問題	
C 1800	SPD error of ROM module	主機板問題	
C 1999	Other hardware error	主機板問題	
C 2000	Software error	主機板問題	